



RESOURCE LOADING CHART rev00

DIRECT MANPOWER LOADING:

S. No	PLANT	UNIT	EQUIPMENT	MAKE	DESCRIPTION	GROUP	SHIFTS / 12 Hrs	SUPERVISOR	WPR	MILLWRIGHT	FITTER	RIGGER I	RIGGER II	TOTAL MANPOWER
1	SPCO	43	EXTRUDER	COPERION	Screw Removal rework due to spare screw wrong assembly	A	3-DAY	1	1	3	3	1	2	22
						B	3-NIGHT	1	1	3	3	1	2	
							6 SHIFTS	2	2	6	6	2	4	22

INDIRECT MANPOWER LOADING:

S. No	Description		Qty.
1	Material Coordinator		1
2	FW/HW		2
TOTAL INDIRECT MANPOWER			3
GRAND TOTAL (DIRECT+INDIRECT) MANPOWER			25

EQUIPMENT & OTHER RESOURCE LOADING:

S. No	Description		Qty
1	Tools & Consumables		1
2	Rigging Tools		1
3	Air Compressor 400 CFM		1
4	40 Feet Trailer		3 shifts
5	40 Feet Low bed Trailer		2 shifts
6	Hydro torquiang crew		3 shifts
7	Fork Lift 10 Ton		1